

Inspection Photos
Location Name: Jerry 1
Location ID: 318569



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Jerry 1
Location ID: 318569



Photo 3 Weeds overgrown around WH

Photo 4 Weeds overgrown around Horizontal Heated Separator.

Inspection Photos
Location Name: Jerry 1
Location ID: 318569



Photo 7 TB sign

Photo 8 Weeds overgrown around TB

Inspection Photos
Location Name: Jerry 1
Location ID: 318569



Photo 9 weeds overgrown in and on TB berm

Photo 10 Weeds overgrown in and on TB berm