

Inspection Photos
Location Name: Gorges 1
Location ID: 318819



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Gorges 1
Location ID: 318819



Photo 3 Pump jack not attached to WH

Photo 4 Horizontal Heated Separator

Inspection Photos
Location Name: Gorges 1
Location ID: 318819



Photo 5 Gas Meter Run no card to indicate calibration status

Photo 6 TB sign

Inspection Photos
Location Name: Gorges 1
Location ID: 318819



Photo 7 TB