

Inspection Photos
Operator: Logos Operating
API: 067-06443
Date: 10/15/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Vegetation is progressing with grasses and shrubs such as western wheatgrass, sand dropseed, and rubber rabbitbrush.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of the reference area comprised of sage brush shrubland and pinyon/juniper mosaic with under story of grasses and forbs such as blue grama, sand dropseed, and snakeweed.