

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601



Photo #2054 from entrance to location.



Photo #2055 from entrance to location.

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601



**Photo #2056 Vegetation growing on secondary containment.**