

Final Reclamation Inspection

October 8, 2020

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 313839

Inspection Document #: 697502069

Morgan County, CO

NENE Section 31 T5N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STROMSOE #1
Location ID: 313839



Photo 1. Photo taken of the western location, facing West. Photo illustrates the Operator has removed equipment. This area still needs to be properly contoured, as this area will be flood irrigated.

Inspection Photos
Location Name: STROMSOE #1
Location ID: 313839



Photo 2. Photo taken of the eastern location, facing North. Photo illustrates the Operator has removed equipment. This area still needs to be properly contoured, as this area will be flood irrigated.