

Inspection Photos

10/19/2020

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 312445

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 312445



Photo 1: Photo taken from the southwest corner of the Location, facing north. Photos 1-2 provide an overview of the Location from north to east. Photos shows unused equipment, equipment not needed for production, or trash debris remains on the Location and interim, and that no interim or final reclamation activities have been conducted on the Location.

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 312445



Photo 3: Photo taken from the northwestern area of the Location. See comments under photo 1.



Photo 4: Photo taken from the north end of the Location, facing east. Photo shows areas documented in previous inspection that were required to be reclaimed pursuant to 1003 interim reclamation requirements. Photo shows unused equipment, equipment not needed for production, or trash debris remains, and that interim reclamation activities (including but not limited to recontouring/regrading, compaction alleviation, revegetation) have not been conducted per 1003 rules.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 312445



Photo 5: Photo taken from the north end of the Location, facing south. See comments under photo 4.



Photo 6: Photo taken from the north end of the Location, facing southwest. See comments under photo 4.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 312445



Photo 7: Photo taken from the northeastern area of the Location. Photo shows cut slopes. See comments under photo 4.



Photo 8: Photo taken from the northeast corner of the Location, facing south. Photos 8-10 provide an overview of the Location from south, southwest to west. Photos also show unused equipment, equipment not needed for production, or trash debris remains on the Location, and that no interim or final reclamation activities have been conducted on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 312445



Photo 9: See comments under photo 8.



Photo 10: See comments under photo 8.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 11: USGS Aerial Imagery Dated 9/2/1980. Well was SPUD 4/4/1980. Photo shows the disturbance area of this Location ~ 5 months post drilling activities.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 12: 8/1993 Google Earth aerial image. Photo shows disturbance area of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312445



Photo 13: 6/2016 Google Earth aerial image. Most recent available Google Earth Imagery. Photo shows disturbance area of the Location subject to final reclamation requirements. Surface Owner appears to have disturbed areas north and northwest of the Location.