

Inspection Photos
Location Name: Razor 11 CPB Tank Battery
Location ID: 436611



Photo 1 – Tank Battery Sign



Photo 2 – Heater Treaters



Inspection Photos
Location Name: Razor 11 CPB Tank Battery
Location ID: 433611



Photo 3 – Produced Water Tanks



Photo 4 – Crude Oil Tanks

Inspection Photos
Location Name: Razor 11 CPB Tank Battery
Location ID: 433611



Photo 5 – Compressor



Photos 6 – Stained Soil at Compressor Drain Pit