

Inspection Photos
Location Name: Razor 11H
Location ID: 430127



Photo 1 – Wellheads



Photo 2 – 11-0241H

Inspection Photos
Location Name: Razor 11H PAD
Location ID: 430127



Photo 3 – Stained Soil at Pumping Unit



Photo 4 – Stained Soil at Pumping Unit

Inspection Photos
Location Name: Razor 11H PAD
Location ID: 430127



Photo 5 – Stained Soil at Pumping Unit