

# Inspection Photos

API: 043-06231

Operator: AUSCO PETROLEUM INC

Inspection Date: 10/16/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020

## Inspection Photos



**Photo 1.** Facing south along the access road. There is erosion occurring down the road which needs to be repaired and stormwater needs to be diverted off the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020



## Inspection Photos



**Photo 2.** Facing southwest toward the access road and location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020

## Inspection Photos



**Photo 3.** Facing southwest toward the location. There is undesirable weeds throughout the location. Interim reclamation has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020



## Inspection Photos



**Photo 4.** Facing south at the location. Unused areas of the location have not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020



## Inspection Photos



**Photo 5.** Facing north at the location. There is undesirable weeds (Russian thistle) throughout the location. The topsoil piles are not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020



## Inspection Photos



**Photo 6.** The topsoil pile are not maintained and have undesirable weeds . The soil piles need to be replaced for interim reclamation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020



## Inspection Photos



**Photo 7.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020



## Inspection Photos



**Photo 8.** Facing southwest toward the production equipment. Undesirable weeds need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/16/2020