

# Inspection Photos

Operator: BP America  
API: 067-08336  
Date: 10/20/2020



Photo 1. View of the project area from the southeastern corner facing center.





Photo 2. View of the eastern fill slope from the well pad entrance facing northward. Revegetation is progressing with intermediate wheatgrass, western wheatgrass, and smooth brome.





Photo 3. View of scattered trash and debris observed within the western project area.





Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with gambel oak, western wheatgrass, prairie junegrass, and Oregon grape in the understory.