

Final Reclamation Inspection

October 13, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 320561

Inspection Document #: 697502083

Adams County, CO

SESE Section 26 T1S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MAUL #44-26
Location ID: 320561



Photo 1. Photo taken from the entrance of the PA well location off Picadily Rd, facing West. Photo illustrates Operator has removed all equipment related to the PA well, removed gravel and has performed seedbed prep.