

# Final Reclamation Inspection

October 13, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 320472

Inspection Document #: 697502085

Adams County, CO

CSE Section 26 T1S R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MAUL #2  
Location ID: 320472



**Photo 1.** Photo taken from the entrance of the associated offsite tank battery, as well as the PA well location off 128th Ave, facing North. Photo illustrates Operator has failed removed all equipment related to the PA well. Operator has removed gravel from the tank battery, well location and access road, and has performed seedbed prep.

Inspection Photos  
Location Name: MAUL #2  
Location ID: 320472



**Photo 2.** Photo taken from the southern well location access road, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: MAUL #2  
Location ID: 320472



**Photo 3.** Photo taken from the associated offsite tank battery, facing West. Photo illustrates Operator has failed removed all equipment related to the PA well.