

Final Reclamation Inspection

October 13, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 320555

Inspection Document #: 697502089

Adams County, CO

NWSE Section 26 T1S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MAUL #33-26
Location ID: 320555



Photo 1. Photo taken from the entrance of the well location off 132nd Ave, facing South. Photo illustrates Operator has removed equipment from the well location and has removed gravel from the well location and access road, and has performed seedbed prep.