

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 1 – Wellhead Sign



Photo 2 – Tank Battery

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 3 – Heater Treater



Photo 4 – ECD and Flare

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 5 – Pumping Unit



Photo 6 – Wellhead, Stained Soil

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 7 – Stained Soil at Gas Engine



Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 9 – Stained Soil at Gas Engine



Photo 10 – Stained Soil at Exhaust

Location ID: 424744

Colorado Oil and Gas Conservation Commission
40.6242, -104.24205, 4940.7ft, 205°
02/21/2001 11:24:05

Photo 11 – Gas Meter Calibration Card

Colorado Oil and Gas Conservation Commission
40.6242, -104.24207, 4936.7ft, 214°
02/21/2001 11:24:00

Photo 12 – Gas Meter Calibration Card