

Interim Reclamation and Stormwater Inspection

October 13, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320137

Inspection Document #: 697502091

Adams County, CO

NWNE Section 17 T1S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPPR-JULIE #1
Location ID: 320137



Photo 1. Photo taken from the tank battery. Photo illustrates Operator sign and which well the tank battery services.

Inspection Photos
Location Name: UPPR-JULIE #1
Location ID: 320137



Photo 2. Photo taken from the tank battery, facing Southwest. Photo illustrates the Operator has performed the previous corrective action to manage weeds.



Inspection Photos
Location Name: UPPR-JULIE #1
Location ID: 320137



Photo 3. Photo taken from the tank battery, facing West. See comments under Photo 2.



Inspection Photos
Location Name: UPPR-JULIE #1
Location ID: 320137



Photo 4. Photo taken from the tank battery, facing West. See comments under Photo 2.

