

Interim Reclamation and Stormwater Inspection

October 13, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320095

Inspection Document #: 697502093

Adams County, CO

SWNE Section 8 T1S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 1. Photo taken from the tank battery, facing West. Photo illustrates Operator has performed the corrective action to manage weeds.



Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 2. Photo taken from the tank battery, facing North. See comments under Photo 1.

