

# Final Reclamation Inspection

October 13, 2020

Operator: HRM RESOURCES II LLC - 10548

Location ID: 318947

Inspection Document #: 697502097

Weld County, CO

NESW Section 28 T1N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CINDY #23-28  
Location ID: 318947



**Photo 1.** Photo taken from the associated tank battery location, facing North. Photo illustrates the Operator has failed to remove all equipment. DCP was nearby on the day of this inspection and indicated that all equipment was going to be removed.

Note: There was no equipment at the well location.

Inspection Photos  
Location Name: CINDY #23-28  
Location ID: 318947



**Photo 2.** Photo taken from the associated tank battery location, facing Southwest. See comments under Photo 1.

Inspection Photos  
Location Name: CINDY #23-28  
Location ID: 318947



**Photo 3.** Photo taken from the associated tank battery location, facing West. See comments under Photo 1.