

Inspection Photos

Operator: BP America
API: 067-08630
Date: 10/20/2020



Photo 1. View of the eastern project area from the northeastern corner facing southward. Fill slope is graveled with scattered grasses such as western wheatgrass and smooth brome.



Photo 2. View of the northern fill slope from the northeastern corner facing westward.



Photo 3. View of musk thistles within the interim reclamation area. Approximately 25 individuals observed.



Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with gambel oak, western wheatgrass, prairie junegrass, and Oregon grape in the understory.