

Inspection Photos

Location Name: UYEMURA-67N64W /31NWSE

Location #: 305099



Photo #1

Uyemura 33-31 (05-123-22441) Wellsite

Producing | PR



Photo #2

Uyemura 34-31, 33-31, Pfenning 43-31, 44-31

Battery site

Active