

Inspection Photos

API: 043-40025

Operator: JAVERNICK OIL

Inspection Date: 10/19/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-40025 | Date: 10/19/2020

Inspection Photos



Photo 1. Facing east toward the location. The vegetation has not established to 80% cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40025 | Date: 10/19/2020

Inspection Photos



Photo 2. Facing north toward the location. The vegetation has not established to 80% cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40025 | Date: 10/19/2020

Inspection Photos



Photo 3. There is still various debris that remains at the location. Photos shows various metal and nails.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40025 | Date: 10/19/2020