

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2020

Submitted Date:

10/22/2020

Document Number:

699102636

FIELD INSPECTION FORM

Loc ID 447617 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447618	TANK BATTERY	AC	09/08/2016		-	GITTLEIN D04-24, Marie D4-72	AC

General Comment:

[This is a follow up to FIRR #402514594. CA's have been corrected.](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adeuqate

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment: Sand Cans			
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		40.247900,-104.554800
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	FIBERGLASS AST		40.247800,-104.555500
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	4	OTHER	BV CONCRETE		,		
Comment: Shares contianment with crude oil tanks.							
Corrective Action:						Date:	
Paint							
Condition							
Other (Content)							
Other (Capacity)	60 BBLs						
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	10	300 BBLs	STEEL AST		40.247800,-104.555500		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 447618 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 10/22/20 at approximately 0903hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402514594 at Gittlein D04-24, Marie D4-72 Tank Battery of Noble Energy, at Facility ID # 447618 in Weld County, Colorado. During this inspection the compliance issues have been corrected to comply with COGCC rules See attached photos. This is a summary of inspection report.</p>	burnsa	10/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102637	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5275598