

## Inspection Photos

Location Name: LOWER HORSE DRAW UNIT #2166

Location ID: 316064 & Remediation Project Number: 7437

Inspection Date: October 13, 2020



Location sign.



Tank battery.



## Inspection Photos

Location Name: LOWER HORSE DRAW UNIT #2166

Location ID: 316064 & Remediation Project Number: 7437

Inspection Date: October 13, 2020



**Wellhead.**



**SVE well with a solar fan.**



## Inspection Photos

Location Name: LOWER HORSE DRAW UNIT #2166  
Location ID: 316064 & Remediation Project Number: 7437  
Inspection Date: October 13, 2020



SVE well with a solar fan and SVE well with a whirlybird.

