

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL 611S90W /24NWSW

Location ID: 324490



Photo #2080 from entrance to location.



Photo #2081 from entrance to location.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL 611S90W /24NWSW

Location ID: 324490



Photo #2082 Inlet of culvert #1.



Photo #2083 Inlet of culvert #1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL 611S90W /24NWSW

Location ID: 324490



Photo #2085 inlet culvert #2.



Photo #2087 outlet culvert #2.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL 611S90W /24NWSW

Location ID: 324490



Photo #2084 Outlet of culvert #1

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL 611S90W /24NWSW

Location ID: 324490



Approximate location of culverts.