

Inspection Photos

Operator: BP America
API: 067-06724
Date: 10/22/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Dense kochia debris needs to be removed and properly disposed of.



Photo 3. View of kochia debris within the eastern project area from the southeastern corner facing northward.



Photo 4. View of the reference area comprised of irrigated grass field. Vegetation is in a grazed condition and not identifiable at this time.