

Inspection Photos

Operator: BP America
API: 067-07188
Date: 10/22/2020



Photo 1. View of the project area from the southwestern corner facing center. Revegetation is progressing with western wheatgrass and smooth brome.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass and smooth brome. Vegetation is partially mowed.



Photo 3. View of Canada thistles in a mowed condition within the southwestern project area. Numbers are reduced and need to be managed.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with gambel oak, junegrass, and penstemon.