

# Inspection Photos

Operator: BP America  
API: 067-08722  
Date: 10/22/2020



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass and sand dropseed.





Photo 3. View of Canada thistles in a mowed condition within the central project area. Continue managing.





Photo 4. View of the reference area comprised of pinyon and juniper woodland with gambel oak, junegrass, squirreltail, and penstemon.