

Inspection Photos
Loc#335444
Operator: Caerus
Inspection #: 692402601
Inspection Date: 10/20/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

October 20, 2020



Photo#2:
Treated area back of Tanks.

October 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus GMU Loc#335444