

Inspection Photos
Loc#436004
Operator: Ursa
Inspection #: 692402122
Inspection Date: 10/20/20



Photo#1:
Overview of Location.

October 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Valley Farms O Pad Loc#436004



Photo#2:

Noxious Weed, Knapweed at South end of pad on either side of Access road

October 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Valley Farms O Pad Loc#436004