

Final Reclamation Inspection

October 22, 2020

Operator: CONTINENTAL RESOURCES INC - 10347

Location ID: 424698

Inspection Document #: 697502103

Weld County, CO

NENE Section 13 T8N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Dunn #1-13H
Location ID: 424698



Photo 1. Photo taken north of the location, facing South. Photo illustrates location was not constructed at the proposed well location based off field observations