

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2020

Submitted Date:

10/26/2020

Document Number:

699102642

FIELD INSPECTION FORM

Loc ID 328555 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248336	WELL	TA	08/01/2018	OW	123-16134	KARCH BLUE D 10-02	TA

General Comment:

[Snow covered ground. Facility Decommissioned.](#)

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Yellow, "LTSI" Variance Tag.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 248336 Type: WELL API Number: 123-16134 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 10/26/20 at approximately 0943hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Karch Blue D10-02 of Noble Energy Location ID: 328555 in Weld County, Colorado. While there, I observed a well that is T/A. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p>	burnsa	10/26/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102643	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5277279