

Construction and Stormwater Inspection

October 22, 2020

Operator: MALLARD EXPLORATION LLC- #10670

Location ID: 455576

Inspection Document #: 697502109

Weld County, CO

NENE Section 33 T8N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Harlequin North /Pad
Location ID: 455576



Photo 1. Photo taken from the entrance of the location off Hwy 14, facing North. Photo illustrates a tracking device BMP. At the time of this inspection, there were no track out issues observed.

Note: tracking device BMPs shall be long enough for a full tire rotation. Since the access road has been sufficiently stabilized with gravel, vehicle track out should be minimized.

Inspection Photos
Location Name: Harlequin North /Pad
Location ID: 455576



Photo 2. Photo taken from the entrance of the location off Hwy 14, facing South. See comments under Photo 1.

Operator will likely have to conduct further reclamation activities along the roadside areas to stabilize and prevent weed establishment.

Inspection Photos
Location Name: Harlequin North /Pad
Location ID: 455576



Photo 3. Photo taken from a portion of the main access road, facing South.
See comments under Photo 2.

Inspection Photos
Location Name: Harlequin North /Pad
Location ID: 455576



Photo 4. Photo taken from the northeastern location, facing South. Photo illustrates the stabilized outlet of the retention pond and hydromulch which has been applied the perimeter of location.



Photo 5. Photo taken from the northeastern location, facing West. See comments under Photo 4.

Inspection Photos
Location Name: Harlequin North /Pad
Location ID: 455576



Photo 6. Photo taken from the northeastern location, facing South. See comments under Photo 4.

Inspection Photos
Location Name: Harlequin North /Pad
Location ID: 455576



Photo 7. Photo taken north of location, facing South. Photo illustrates drilling operations are underway.