

Interim Reclamation and Stormwater Inspection

October 22, 2020

Operator: CONFLUENCE DJ LLC- #10518

Location ID: 457632

Inspection Document #: 697502111

Weld County, CO

NESE Section 7 T7N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 1. Photo taken from the entrance of location. Photo illustrates the Operator sign.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 2. Photo taken from the well, facing North. Photo illustrates unmanaged weeds (Kochia and Russian thistle) throughout the entire location.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 3. Photo taken from the well, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 4. Photo taken from the well, facing Southwest. See comments under Photo 2.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 5. Photo taken from the well, facing Northwest. See comments under Photo 2.