

**Inspection Photos**  
**Location Name: Dwinell 1**  
**Location ID: 324591**



**Photo 1. Overview of location taken at entrance facing east.  
Freshly disturbed soil with no stormwater controls.**



**Photo 2. Freshly disturbed soil with no stormwater controls.**



**Inspection Photos**  
**Location Name: Dwinell 1**  
**Location ID: 324591**



**Photo 3. Example of stained soil in tank battery.**



**Photo 4. Example of stained soil in tank battery.**

**Inspection Photos**  
**Location Name: Dwinell 1**  
**Location ID: 324591**



**Photo 5. Example of stained soil behind tank battery.**



**Photo 6. Example of debris on location.**