

# Construction and Stormwater Inspection

October 22, 2020

Operator: NGL WATER SOLUTIONS DJ LLC- #10373

Location ID: 450612

Inspection Document #: 697502113

Weld County, CO

SWNW Section 35 T7N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NGL #C10B  
Location ID: 450612



**Photo 1.** Photo taken from the southwestern location, facing Northeast. Photo illustrates unmanaged weeds (Kochia and Russian thistle) throughout the location.

Inspection Photos  
Location Name: NGL #C10B  
Location ID: 450612



**Photo 2.** Photo taken from the southwestern location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: NGL #C10B  
Location ID: 450612



**Photo 3.** Photo taken from the southwestern location, facing North. Photo illustrates the topsoil stockpile has only been temporarily stabilized.