

Inspection Photos
Loc#413453
Operator: Grizzly
Inspection #: 692402605
Inspection Date: 10/20/20





Photo#1:

Debris has been removed. Knapweed (B list Noxious weed) is established along South perimeter .

October 20, 2020