

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #1 – Aerial photo provided by Operator (doc #402505121) to document Spill/Release ID #478242. Blue area of photo depicts reported flow path of spill.

Note: fluids released by the subject spill were reported to flow from south to north, into the lined pit depicted in this photo.

Photo #2 – Photo of residual hydrocarbon impacts around the point of release (POR) of Spill/Release ID #478242.

The following field photos depict residual hydrocarbon impacts underlying equipment along the flowpath and are presented from south to north.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #3 - Photo of residual hydrocarbon impacts around the point of release (POR) of Spill/Release ID #478242.




Photo #4 - Photo of residual hydrocarbon impacts around the point of release (POR) of Spill/Release ID #478242.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #5 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



Photo #6 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #7 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



Photo #8 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #9 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



Photo #10 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #11 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



Photo #12 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #13 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



Photo #14 - Photo of residual hydrocarbon impacts along flowpath of Spill/Release ID #478242.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Tank Battery & Central Tank Battery Spill

Location ID: #449640 & Spill/Release ID: #478242

Inspection Date: October 23, 2020



Photo #15 – Operator had staff onsite to remove materials from lined pit on inspection date.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources