

BP L48 San Juan



## V2 Compliance Follow Up Form

18158395024

**Reference Number:**

**Form Name:**

**Submitter Name:**

**Submission Date:**

**Location:**

20201013-18158395024

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Oct 13, 2020 3:09:50 PM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Oct 13, 2020 3:09:25 PM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

**Name**

colen@horizonenvservices.com

**Date**

Oct 13, 2020

**Well Name**

WRIGHT GAS UNIT 01-19 1

**API Number**

50670635600

**Select State**

Colorado

**Work type**

COGCC Inspection AR

**Action Complete**

Other

**Photo of first corrective action completed**





**Completed work description Corrective  
Action 1**

Selectively treated Canada thistle populations.

**Photo of second corrective action completed****Completed work description of corrective  
action 2**

Selectively treated Canada thistle populations.

**Photo of third corrective action completed****Completed work description of corrective  
action 3**

Selectively treated Canada thistle populations.

**Photo of fourth corrective action completed**



**Completed work description**

Selectively treated Canada thistle populations.

**Completed work description of corrective action 4**

Selectively treated Canada thistle populations.

**Additional photos****Additional photos**



**Completed work description**

Selectively treated Canada thistle populations.

**Summary of all work completed**

Selectively treated Canada thistle populations.