

BP L48 San Juan



V2 Compliance Follow Up Form

18158394170

Reference Number: 20201013-18158394170
Form Name: V2 Compliance Follow Up Form
Submitter Name: Cole Nichols (colen@horizonenvservices.com) | colen@horizonenvservices.com
Submission Date: Oct 13, 2020 3:06:46 PM MDT
Location: 91 S Skylane Dr, Durango, CO 81303, USA
Oct 13, 2020 3:10:17 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name colen@horizonenvservices.com
Date Oct 13, 2020
Well Name LUNT GAS UNIT 19-01 3
API Number 50670951200
Select State Colorado
Work type COGCC Inspection AR
Action Complete Other

Photo of first corrective action completed



Completed work description Corrective Action 1

Selectively treated Russian knapweed populations.

Photo of second corrective action completed



Completed work description of corrective action 2

Selectively treated Russian knapweed populations.

Photo of third corrective action completed



Completed work description of corrective action 3

Selectively treated Russian knapweed populations.

Photo of fourth corrective action completed




Completed work description

Selectively treated Russian knapweed populations.

Completed work description of corrective action 4

Selectively treated Russian knapweed populations.

Additional photos



Additional photos



Completed work description

Selectively treated Russian knapweed populations.

Summary of all work completed

Selectively treated Russian knapweed populations.