

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



**Photo 1 – Pumping Unit – Stained Soil, WEEDS, Debris,
Unused Equipment**



**Photo 2 – Pumping Unit – Stained Soil, WEEDS, Debris,
Unused Equipment**

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo 3 – Pumping Unit – Stained Soil, WEEDS, Debris, Unused Equipment



Photo 4 – Pumping Unit – WEEDS, Debris, Unused Equipment

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo 5 – Unused Equipment at Manifold



Photo 6 – Tank Battery Sign - WEEDS

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo 7 – Heater Treater – Weeds



Photo 8 – Stained Soil at Heater Treater – Weeds

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo 9 – Pit Area – Weeds



Photo 10 – Pit Area – Weeds

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo 11 – Tank Battery – Berms Inadequate, Weeds



Photo 12 – Tank Battery – Berms Inadequate, Weeds