

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 1 – Tank Battery Sign at Entrance



Photo 2 – Pumping Unit – Stained Soil, WEEDS, Debris, Unused Equipment

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Colorado Oil and Gas Conservation Commission
40.4405, -104.16931, 4592.2ft, 189°
10/07/2020 11:16:42

Photo 3 – Pumping Unit – Stained Soil, WEEDS, Debris, Unused Equipment



Colorado Oil and Gas Conservation Commission
40.44044, -104.16954, 4595.6ft, 92°
10/07/2020 11:17:02

Photo 4 – Engine House – Stained Soil

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 5 – Unused Tubing Southside of Pit



Photo 6 – Tank Battery – Berms Inadequate, Weeds, Rusted Tanks

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 7 – Tank Battery – Berms Inadequate, Weeds, Rusted Tanks



Photo 8 – Heater Treater – Weeds

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo 9 – Heater Treater – Weeds



Photo 10 – Pumping Unit – Weeds, Debris, Trash

Inspection Photos
Location Name: Behring #1
Location ID: 317496



Photo 11 – Pit Area – WEEDS



Photo 12 – Pit Area - WEEDS