

# *Inspection Photos*

*API#045-06608*

*Operator: Chevron*

*Inspection Number: 692400009*


*Inspection Date: 7/25/2018*



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



Photo#1:  
GE Aerial view of Location.

July 25, 2018



Photo#2:  
View over Pad area to Northwest.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA 65-12D API#045-06608



Photo#3:  
Portions of Pad area, bare of vegetation.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Shale API#045-06593



**Photo#5:**  
Revegetated area of Pad.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA 65-12D API#045-06608



**Photo#4:**  
View over Location to Southeast.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA 65-12D API#045-06608



**Photo#6:**  
Berms (topsoil) , not revegetated & appear to be used for livestock loafing areas.



**Photo#7:**  
Berms (topsoil) , not revegetated & appear to be used for livestock loafing areas.

July 25, 2018



**Photo#8:**  
Aerial showing four Chevron Variance Requests. Subject Well #3 Balloon.

July 25, 2018