

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2020

Submitted Date:

10/27/2020

Document Number:

689804865

FIELD INSPECTION FORM

 Loc ID 313092 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10559
 Name of Operator: SOUTHLAND ROYALTY COMPANY LLC
 Address: 400 WEST 7TH STREET
 City: FORT WORTH State: TX Zip: 76102
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Blaylock, Connie		cblaylock@mspartners.com	
Gallenbeck, Danny		dgallenbeck@ctfieldsvcs.com	
Elgin, Jerry		jelgin@mspartners.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223584	WELL	SI	08/01/2018	GW	081-06951	BLUE SKY 1-44	SI

General Comment:

Inspector on location to witness MIT.

Inspected Facilities

Facility ID: 223584 Type: WELL API Number: 081-06951 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Inspector on location to witness MIT. Form 42 document number 402509342. Tubing at 275 psi. Casing pressured to 420 psi and held for 15 minutes.

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689804866	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5278371