

**Inspection Photos**  
**Location Name: Surprise-Damfino S6 Pad**  
**Location ID: 416625**



**Photo 1. Overview of location taken facing southeast.**



**Photo 2. Example of erosion onto location and silt fence becoming debris.**

