

# *Inspection Photos*

*API#045-06593*

*Operator: Chevron*

*Inspection Number: 692400010*

*Inspection Date: 7/25/2018*



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



Photo#1:  
GE Aerial view of Location.

July 25, 2018



Photo#2:

Overview of Location from entry to North. Insert of Mullein plant that had been treated.

July 25, 2018



Inspection Photos: Chevron PA Shale API#045-06593



Photo#3:  
Overview of Location from top of Cut to South

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Shale API#045-06593



**Photo#4:**  
Portions of Pad and Fill Slope that have re-vegetated.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Shale API#045-06593



**Photo#5:**  
Bermed (topsoil) appears to be used for livestock access and loafing area.

July 25, 2018




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#6:**  
View along Cut Slope.

Inspection Photos: Chevron PA Shale API#045-06593



**Photo#7:**  
Aerial showing Four Chevron Variance Requests. Subject Well #1 Balloon.

July 25, 2018