

# *Inspection Photos*

*API#045-06594*

*Operator: Chevron*

*Inspection Number: 692400008*

*Inspection Date: 7/25/2018*



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



Photo#1:  
GE Aerial view of Location.

July 25, 2018



Photo#2:  
View of Pad area to Southwest.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Shale API#045-06594



Photo#3:  
Portions of Pad area, bare of vegetation.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Shale API#045-06594



**Photo#4:**  
Portions of Pad area, that have re-vegetated.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Shale API#045-06594



**Photo#5:**  
Bermed (topsoil) appears to be used for livestock access and loafing area.



**Photo#6:**  
Bermed (topsoil) appears to be used for livestock access and loafing area.

July 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Shale API#045-06594



Photo#7:  
Aerial showing Four Chevron Variance Requests. Subject Well #4 Balloon.

July 25, 2018