

Inspection Photos
Location Name: Simoes 12-30
Location ID: 428571



Photo 1. Overview of location taken facing southwest. Dried annual weeds and equipment stored on location.



Photo 2. Dried annual weeds on access road.

