

Final Reclamation Inspection

October 28, 2020

Operator: HRM RESOURCES II LLC - 10548

Location ID: 313929

Inspection Document #: 697502117

Morgan County, CO

SWSE Section 14 T1N R56W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources




Photo 1. COGCC GISOnline 2019 aerial imagery illustrates the operator has failed to reclaim ~0.30 miles of road.

Inspection Photos
Location Name: JANET #2
Location ID: 313929



Photo 2. Photo taken from the southern access road, facing West. Photo illustrates the Operator has failed to reclaim the access road.

Inspection Photos
Location Name: JANET #2
Location ID: 313929



Photo 3. Photo taken from the western access road, facing East. Photo illustrates the Operator has failed to reclaim the access road.

Inspection Photos
Location Name: JANET #2
Location ID: 313929



Photo 4. Photo taken from the northern access road, facing West. Photo illustrates the Operator has failed to reclaim the access road.

Inspection Photos
Location Name: JANET #2
Location ID: 313929



Photo 5. Photo taken from the well location, facing North. Photo illustrates an ~45'x~65 area where the pump jack was located has not been reclaimed. The well location is bare of vegetation.

Inspection Photos
Location Name: JANET #2
Location ID: 313929



Photo 6. Close up photo of the well location, illustrating the bare ground.

Inspection Photos
Location Name: JANET #2
Location ID: 313929



Photo 7. Reference photo taken north of the well location, facing North. Photo illustrates blue grama, purple three-awn, and sand sage.

Inspection Photos
Location Name: JANET #2
Location ID: 313929



Photo 8. Close up reference photo taken north of the well location.