

Inspection Photos
Operator: Kinder Morgan
API: 083-06287
Date: 10/27/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush, sagebrush, and western wheatgrass.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of the reference area comprised of mixed sagebrush shrubland and pinyon/juniper woodland with understory of yucca, Indian ricegrass, purple threeawn, and ephedra.