

Inspection Photos
Operator: Kinder Morgan
API: 083-06286
Date: 10/27/2020



Photo 1. View of the project area from the northeastern corner facing center. Well pad needs reclamation.



Photo 2. View of the northern portion of the interim reclamation area from the northeastern corner facing westward.



Photo 3. View of equipment and materials that remain within the project area.



Photo 4. View of risers along the eastern edge of the project area.



Photo 5. View of the reference area comprised of pinyon/juniper woodland with understory of shrubs, forbs, and grasses such as yucca, sagebrush, mountain mahogany, Indian ricegrass, purple threeawn, rock goldenrod, and ephedra.