

**Inspection Photos**  
**Operator: Kinder Morgan**  
**API: 083-06684**  
**Date: 10/27/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western portion of the interim reclamation area from the southwestern corner facing northeastward. Revegetation is progressing, largely with rubber rabbitbrush and Indian ricegrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of pinyon/juniper woodland with understory of shrubs, forbs, and grasses such as yucca, sagebrush, mountain mahogany, Indian ricegrass, purple threeawn, rock goldenrod, and ephedra.